SCHMIDT
control instruments

MZ1 /MZH / MZB1 -232 Sensor to PC
outputs: RS-232

e.g. MZ1-232

e.g. EK0640 cable (3,0 m)

→ Signal RS-232 →

AC Adapter
Power 230 V

← Power ←

SUB-D 25/9 to Com-Port

optional EK0643 cable (2,0 m)
only needed if SUB-D 25 / 9 plug is not
connected direct to the PC

← Signal RS-232 ←

to COM Port
or optional EBG510
Adapter RS-232 to USB

Software: Tension Inspect 3