

## Digital torque driver **DID-4** Various functions Display section one apparatus

Yes-no decision conditions etc. can save five channels.

.. A channel is only changed even if bolting conditions change.

It is not necessary to reset up a maximum value and a minimum value one by one like former.



- The torque screwdriver is Ergonomic and light weight, yet ruggedly constructed
- Peak, Real Time and Peak Down measuring mode (selectable)
- 800 data memory
- Programmable High and Low set points with both audible beep and Green/Red LED indicator for uniform torque tightening or GO/NO GO testing
- Programmable screw tightening counter
- Programmable Auto Zero function resets unit to zero for easy operation
- Both CW and CCW operation
- ASCII format output (USB)
- Runs on internal NiMH batteries (for 12 hours) Auto shut-off after 10 min. of non-use



## Specification

Mode   PD   descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum, of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)	Specification			
Accuracy   ±0.5% (499 or less digit±3digit)     Display   The 4 figures digital display of LCD     The measurement   CW-CCW (right and left)     Measurement   PP   peak to peak   The highest value of load is hold-displayed.     TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   of memory data are displayed.     Bata output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Option   When outputting da	Model Formula			
Display   The 4 figures digital display of LCD     The measurement direction   CW-CCW (right and left)     Measurement Mode   PP   peak to peak   The highest value of load is hold-displayed.     TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 16 is second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge about 3 hour /, continuation about 12-hour use   Auto-power-off     Atter the neglect during 10 minutes   Bit #1+, #2+     Accessories (one piece each)   Bit #1+, #2+     Accessories (one piece each)   Exclusive charger	Measuring range			
Display   The 4 figures digital display of LCD     The measurement direction   CW-CCW (right and left)     Measurement Mode   PP   peak to peak   The highest value of load is hold-displayed.     TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 16 is second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge about 3 hour /, continuation about 12-hour use   Auto-power-off     Atter the neglect during 10 minutes   Bit #1+, #2+     Accessories (one piece each)   Bit #1+, #2+     Accessories (one piece each)   Exclusive charger			±0.5% (499 or less digit±3digit)	
direction   CW-CCW (right and left)     Measurement Mode   PP   peak to peak   The highest value of load is hold-displayed.     TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MI chargeable battery 1.2V×4/cells 800mAh     Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+ Exclusive charger (one piece each)   Exclusive charger Result of calibration document Certification on calibration document Certification on calibrat				
Measurement Mode   PP   peak to peak   The highest value of load is hold-displayed.     TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure Judging function   Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Exclusive charger     (one piece each)   Result of calibration document Certification on calibration document / Traceability system figure			CN/ CN/ (right and loft)	
Measurement Mode   TR   track   A display also changes with load change.     PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit // Socket part   HEX 6.35     Weight   400g     Accessories (one piece each)   Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	direction			
Measurement Mode   PD   peak-down descent from a rise. C   Real-time Output descent from a rise. C   Real-time Output Real-time Output bescent from a rise. C   Real-time Output Real-time Output Five-set preservation is possible. The Maximum, minimum, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     Result of calibration document Certification on calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed. <th></th> <th>PP</th> <th>peak to peak The highest value of load is hold-displayed.</th>		PP	peak to peak The highest value of load is hold-displayed.	
Mode   PD   peak-down   Load catches and displays the moment included in descent from a rise.     C   Real-time Output   Load torque value is outputted every about1/ 160 second.     A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5 interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     Cardination on calibration document   Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB minB) is needed.		TR	track A display also changes with load change.	
A success or failure judging function   High and low value are measurement within the limits, and can be set up. Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     Corption   When outputting data, the cable(USB miniB) is needed.		PD		
judging function   Five-set preservation is possible.     The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     Result of calibration document   Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.		С	<b>Real-time Output</b> Load torque value is outputted every about1/ 160 second.	
The Maximum, minimum, and the average value   The data number, the maximum, the minimum value, and the average value of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Exclusive charger     (one piece each)   Result of calibration document     Certification on calibration document   Certification on calibration document     Option   When outputting data, the cable(USB miniB) is needed.	A success or failure		High and low value are measurement within the limits, and can be set up.	
and the average value   of memory data are displayed.     Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     (one piece each)   Result of calibration document     Certification on calibration document / Traceability system figure   Option     When outputting data, the cable(USB miniB) is needed.   Source of the second of the secon				
Data memory counts   800 data     Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Accessories (one piece each)   Bit #1+, #2+     Option   When outputting data, the cable(USB miniB) is needed.				
Data output   ASCII format (baud rate 19200)     auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+   Exclusive charger     Result of calibration document   Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	and the average value		of memory data are displayed.	
auto clear time   If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Accessories (one piece each)   Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Data memory counts		800 data	
auto clear time   0.0~3.0 seconds (0.5s interval).     Setup of count   1 to 99 count (count in a clockwise direction)     Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Accessories (one piece each)   Bit #1+, #2+     Option   When outputting data, the cable(USB miniB) is needed.	Data output		ASCII format (baud rate 19200)	
Power supply   Ni-MH chargeable battery 1.2V×4cells 800mAh     Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Bit #1+, #2+     Accessories (one piece each)   Bit #1+, #2+     Exclusive charger (one piece each)   Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	auto clear time		If the set-up time comes, measurement value will be automatically cleared in $0.0\sim3.0$ seconds (0.5s interval).	
Charge time / use time   Charge about 3 hour /, continuation about 12-hour use     Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Accessories (one piece each)   Bit #1+, #2+     Exclusive charger (one piece each)   Exclusive charger     Option   When outputting data, the cable(USB miniB) is needed.			1 to 99 count (count in a clockwise direction)	
Auto-power-off   After the neglect during 10 minutes     Bit / Socket part   HEX 6.35     Weight   400g     Accessories (one piece each)   Bit #1+, #2+     Exclusive charger (one piece each)   Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Power supply		Ni-MH chargeable battery 1.2V×4cells 800mAh	
Bit / Socket part   HEX 6.35     Weight   400g     Accessories (one piece each)   Bit #1+, #2+     Exclusive charger (one piece each)   Exclusive charger     Option   Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Charge time / use time		Charge about 3 hour /, continuation about 12-hour use	
Weight   400g     Accessories (one piece each)   Bit #1+, #2+     Exclusive charger (one piece each)   Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Auto-power-off		After the neglect during 10 minutes	
Accessories (one piece each)   Bit #1+, #2+ Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Bit / Socket part		HEX 6.35	
Accessories (one piece each)   Bit #1+, #2+ Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.	Weight		400g	
(one piece each)   Result of calibration document     Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4			Bit #1+, #2+	
Certification on calibration document / Traceability system figure     Option   When outputting data, the cable(USB miniB) is needed.     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4     Image: CEDAR mode D = 4   Image: CEDAR mode D = 4   Image: CEDAR mode D = 4	Accessories		Exclusive charger	
Option When outputting data, the cable(USB miniB) is needed.	(one piece each)			
	Option		When outputting data, the cable(USB miniB) is needed.	
264	Outside-dimension			
m/r			m/m	

## Please check the newest information and the details of each product in a homepage. **《URL http://www.cedar.co.jp》**



Egerate Elektronik URL http://www.egerate.com E-Mail info@egerate.com





The contents of a catalog may change specification and a design without a preliminary announcement.