


Tension Sensor Model TSB2-500 / TSB2-1000



Dimensions in mm



Specifications subject to change without notice!

Hans Schmidt & Co GmbH
P. O. B. 1154
84464 Waldkraiburg Germany


Phone: int. + 49 / (0)8638 / 9410-0
Fax: int. + 49 / (0)8638 / 4825

e-mail: info@hans-schmidt.com
Internet: http://www.hans-schmidt.com

Tension Sensor Model TSB2-2000 / TSB2-5000 / TSB2-10K



Dimensions in mm





Specifications subject to change without notice!

Hans Schmidt & Co GmbH
P. O. B. 1154
84464 Waldkraiburg Germany


Phone: int. + 49 / (0)8638 / 9410-0
Fax: int. + 49 / (0)8638 / 4825

e-mail: info@hans-schmidt.com
Internet: http://www.hans-schmidt.com

Tension Sensor Model TSB2-20K / TSB2-50K



Dimensions in mm





Specifications subject to change without notice!

Hans Schmidt & Co GmbH
P. O. B. 1154
84464 Waldkraiburg Germany


Phone: int. + 49 / (0)8638 / 9410-0
Fax: int. + 49 / (0)8638 / 4825

e-mail: info@hans-schmidt.com
Internet: http://www.hans-schmidt.com

Tension Sensor Model TSB2-100K



Dimensions in mm



Specifications subject to change without notice!

Hans Schmidt & Co GmbH
P. O. B. 1154
84464 Waldkraiburg Germany

Phone: int. + 49 / (0)8638 / 9410-0
Fax: int. + 49 / (0)8638 / 4825

e-mail: info@hans-schmidt.com
Internet: http://www.hans-schmidt.com