




1xFS-WL + max. 3xFS-422 – Sensor to SC-PM4-WL to PC

outputs: RS 422, USB, analog and alarm



Hans Schmidt & Co GmbH

P. O. B. 1154

84464 Waldkraiburg Germany

Phone: int. + 49 / (0)8638 / 9410-0

Fax: int. + 49 / (0)8638 / 4825

e-mail: info@hans-schmidt.com

Internet: <http://www.hans-schmidt.com>

1 FS1-WL Sensor and max. 7 FS1-422 to PC

