


TS1-A10 Sensor without integrated amplifier with Strain gauge amplifier SCV-1-A3

outputs: Current output 4 - 20 mA



MZ-A10 Sensor without integrated amplifier with Strain gauge amplifier SCV-1-A3

outputs: Current output 4 - 20 mA

