



Force Gauge ZTS-DPU/ ZTA-DPU

Force Gauge ZTS/ZTA




Load Cell DPU 2 N to 500 N



Model	Measuring Range	A	B	C	D	E	Measuring Shaft
DPU-2N	2 N	71	57	12	26	32	M 6
DPU-5N	5 N						
DPU-10N	10 N						
DPU-20N	20 N	73	59	7.5	33	39	
DPU-50N	50 N						
DPU-100N	100 N						
DPU-200N	200 N						
DPU-500N	500 N						

Load Cell DPU 1000 N to 20K



Model	Measuring Range	A	B	C	D	E	F	G	Measuring Shaft
DPU-1000N	1000 N	85	58	20	24	40	M12 P1.75 Depth 15	M5 Depth 8	M 10
DPU-2000N	2000 N								
DPU-5000N	5000 N								
DPU-10K	10 kN	105	78	32	36	39	M18 P1.5 Depth 22	M6 Depth 10	ohne
DPU-20K	20 kN	110	88	35	40				